


# MARINE POLLUTION SURVEILLANCE REPORT



Analysis Provided by: The National Oceanic and  
Atmospheric Administration/National Environmental  
Satellite, Data and Information Service (NOAA/NESDIS)

REPORT DATE: JUNE 12, 2013

REPORT TIME: 0007Z (6/11/2013 1907 CDT)

ANALYST: SALEMI

DATA SOURCE: AQUA MODIS

MODE: Multispectral

RESOLUTION: 250 meter

IMAGE DATE/TIME: 6/12/2013 0007Z (6/11/2013 1907 CDT)

## Legend



Possible Oil



False-Positives (not oil)



Destroyed Taylor Platform :  
[ 28°56'9" N / 88°58'12" W ]

REMARKS: Possible emission of oil from the destroyed Taylor platform can be seen moving to the north in visible imagery with sunglint. Clouds in the area make detection of full extent difficult leading to medium-high confidence in polygon shape.

89°30'W


89°0'W

88°30'W

29°30'N

29°0'N

28°30'N



Possible Oil

0 3.5 7 14 21 28 Miles

0 1.53 6 9 12 Nautical Miles

0 4.258.5 17 25.5 34 Kilometers

