

# MARINE POLLUTION SURVEILLANCE REPORT



Analysis Provided by: The National Oceanic and  
Atmospheric Administration/National Environmental  
Satellite, Data and Information Service (NOAA/NESDIS)

REPORT DATE: AUGUST 08, 2014

REPORT TIME: 2346Z (1846 CDT)

ANALYST: SALEMI



DATA SOURCE: AQUA MODIS

MODE: Multispectral

RESOLUTION: 250 meter

IMAGE DATE/TIME: 8/8/2014 1905Z (1405 CDT)

## Legend

-  Possible Oil
-  False-Positives (not oil)
-  Destroyed Taylor Platform :  
[ 28°56'9" N / 88°58'12" W ]

21 km<sup>2</sup> Area of Possible Oil

REMARKS: An area of possible oil extends 15km south and east of the destroyed Taylor platform location. With the white appearance against the dark background and given this is a known repeat leak source, confidence is high the anomaly is oil. The oil extends toward another feature which has a darker appearance and may be due to bathymetry.

